

BUY WISE™ **DID YOU KNOW?**



now in stock!


CONTITECH Drive Belts

ContiTech offers thousands of Serpentine Belt sizes to choose from, plus these belts are OE on many of the world's finest automobiles including Audi, BMW, Chrysler, Fiat, Ford, GM, Kia, Lotus, Maserati, Mercedes Benz, Nissan, Porsche, Rolls Royce, Saab, Volkswagen, and Volvo.

now in stock!

CASTROL EDGE **Synthetic Motor Oils**

10w30, 10w40, 5w20, 5w30, 5w40



now available!

ACDELCO GM **Brake Pipe** **Assembly Kits**

With ACDelco there is a way to make certain hydraulic brake pipe repairs easier. New ACDelco GM Original Equipment (GM OE) hydraulic brake pipe kits can be used any time the entire brake pipe assembly must be replaced due to corrosion or wear.

ACDelco



BUY WISE™
AUTO PARTS *pronto*



Union - Kenilworth
Clifton
800.672.1909

Jersey City
800.399.5072
buywiseautoparts.com

BUY WISE™ DID YOU KNOW?

Now Stocking....!

ADVICS



***Advics Friction for most
ASIAN applications including
OEM Toyota and
Advics Rotors for OEM Toyota!***

To compliment our other Brake Offerings:

ACDelco

Motorcraft

***Making Buy Wise
your "One-Stop"
Brake Source!***

אקדלכו

PAGID

Bendix

pronto

FERODO
THE FIRST NAME IN BRAKES

WAGNER
Brake Products

BUY WISE™
AUTO PARTS **pronto**

Union - Kenilworth
Clifton
800.672.1909

Jersey City
800.399.5072
buywiseautoparts.com

MONROE

BUY WISE™

DID YOU KNOW?

ALL IN STOCK!

OCCUPANCY SENSOR

NEW TO THE AFTERMARKET



IMPORT
601-004

Lexus 2013-05, Scion 2013-05, Toyota 2013-08

Original sensor is highly failure prone, and fits a very broad range of vehicles
Sensor determines the presence of a passenger and turns on the airbag

FAILURE MODE:
• Water intrusion and electrical faults
• Failure results in the passenger air bag light staying on

INTAKE MANIFOLDS

LINE EXTENSION



615-290

Buick 2005-02, Chevrolet 2005-00, Oldsmobile 2004-00, Pontiac 2005-00

OVER 50 SKUS AVAILABLE

A direct replacement for an extremely popular application
Supplies fuel and air mixture to engine cylinders

FAILURE MODE:
• Original unit warps and cracks from heat
• Failure results in port leaks, vacuum leaks and illumination of the check engine light

STEERING SHAFTS

LINE EXTENSION

OVER 45 SKUS AVAILABLE



425-177

Chevrolet C3500 2002-08, Chevrolet C3500HD 2002-09, GMC C3500 2000-08, GMC C3500HD 2002-09

Re-engineered design provides improved alternative over failure-prone original part
Restores steering to the proper function

DORMAN ENGINEERED - Double-D design improves durability and eliminates dunking



FAILURE MODE:
• Clunking and/or binding in the steering column

SUSPENSION SENSOR

NEW TO THE AFTERMARKET



924-261

Ford Expedition 2006-03, Lincoln Navigator 2006-03

Highly failure prone original part, now available in the aftermarket

Direct replacement sensor restores ability to detect/adjust vehicle suspension height

COMPLETE KIT - Includes all hardware for a complete repair



FAILURE MODE:
• Wears over time
• Failure results in the sensor being unable to detect the correct vehicle height

CAM PHASERS

LINE EXTENSION

OVER 10 SKUS AVAILABLE



917-274

Buick 2013-08, Cadillac 2013-07, Chevrolet 2013-08, GMC 2013-09, Pontiac 2009-07, Saturn 2010-07, 3.0L, 3.6L, Exhaust Position

Direct replacement for an extremely popular application
Adjusts cam shaft timing for optimal engine performance and efficiency

FAILURE MODE:
• Oil passages clog with sludge
• Failure results in loss of power in the engine accompanied by a knocking sound and Diagnostic Trouble code displayed

INTAKE MANIFOLD RUNNER CONTROLS [IMRC]

LINE EXTENSION

OVER 10 SKUS AVAILABLE



911-912

Ford Expedition, F-Series Trucks 2013-04, Lincoln Mark LT, Navigator 2013-05

Optimizes power and torque across various ranges of engine speed operation to improve overall engine performance and fuel economy

FAILURE MODE:
• Runners become stuck open or closed
• Failure results in illumination of the check engine light

OIL COOLER KITS

LINE EXTENSION

OVER 5 SKUS AVAILABLE



DIESEL
904-226

Ford F Super Duty 1994-92, Ford F-250 1994-92, Ford F-350 1994-92, Ford F59 1997-92, 7.3L

Prevents fluid leaks and the engine from overheating

COMPLETE KIT - Includes all O-rings and gaskets for a complete repair



FAILURE MODE:
• Gaskets become brittle and cooler becomes dogged
• Failure results in coolant leaks and high engine temperatures

HARMONIC BALANCER BOLT

NEW TO THE AFTERMARKET

FITS HARMONIC BALANCERS



917-139

GM 2013-08, Saab 2009-05

Substantial high selling opportunity with broad range of applications

Required when servicing any part that needs the harmonic balancer to be removed, such as timing covers

Original bolts cannot be reused

FAILURE MODE:
• Rust and corrosion
• Failure results in increased vibration and noise

DID YOU KNOW?



Has Added....The Following New Product Lines To Our Vast Inventory Mix!

AISIN

Geared up for the future



Plus....We're

GOING GREEN

We're Emailing and Faxing
Statements / Credits /
Copies of Invoices
WANT IN...JUST ASK!*



Our emails are sent from:
visionserver@samuelsinc.com
Please be sure to check your spam folder if you are
not receiving them!